



Capability List
 Approved for Operations Specifications
 Revision N
 Dated June 07, 2022

2133 Aviation Drive Upland,
 CA 91786
 PH: 909-981-0895 FAX: 909-981-0962
 FAA CRS Q2TR970X EASA 145.5940

| Manufacturer | Model | Capability | Nomenclature | Part Number | CMM/ATA | Date |
|-------------------------|-------------------------|--|--|-------------------------------------|----------------------------------|------------|
| Hamilton Sundstrand | B1900 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 775624-1 | CMM 21-51-34 | 12/7/2005 |
| Honeywell | Dornier 328 | Inspect, Overhaul, Repair and Test | Cold Air Unit | 1716D000-00X Alt PN: 1762D00-00X | CMM 21-51-11 | 1/17/2018 |
| Honeywell | Dornier 328 | Inspect, Overhaul, Repair and Test | Pneumatic Temperature Sensor | 5677C000-00X | CMM 21-51-16 | 1/17/2018 |
| Honeywell | Dornier 328 | Inspect, Overhaul, Repair and Test | Condenser/ Water Extractor | 8563C000 | CMM 21-51-13 | 1/17/2018 |
| Honeywell | Dornier 328 | Inspect, Overhaul, Repair and Test | Turbine Inlet Control Valve | 5732C000 | CMM 21-51-15 | 1/17/2018 |
| Garrett Airesearch | 1124 Westwind* | Overhaul, Repair, Inspect and Test | Two-inch Diameter Electric Shutoff Valve | 321760-series | Report 4A-103 RS QTC-2016-001 | 10/26/2016 |
| Honeywell (Aireasearch) | A-300/A-310 DC-10/MD-11 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 187900-6 | CMM 21-53-24 | 1/30/2009 |
| Honeywell (Aireasearch) | A-300/A-310 DC-10/MD-11 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 187900-7 | CMM 21-53-24 | 1/30/2009 |
| Honeywell (Aireasearch) | A-300/A-310 DC-10/MD-11 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 187900-8 | CMM 21-53-24 | 1/30/2009 |
| Honeywell (Aireasearch) | A-300/A-310 DC-10/MD-11 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 187900-9 | CMM 21-53-24 | 1/30/2009 |
| Honeywell (Aireasearch) | A-300/A-310 DC-10/MD-11 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 187900-10 | CMM 21-53-24 | 1/30/2009 |
| Liebherr | A320 | Inspect, Overhaul, Repair and Inspect (Test) | Reheater | 755A0000-04 | CMM 21-51-08 | 8/22/2008 |
| Liebherr | A320 | Inspect, Overhaul, Repair and Inspect (Test) | Reheater | 755A0000-04 Amdt A | CMM 21-51-08 | 8/22/2008 |

| | | | | | | |
|---------------------|--|--|-------------------------------|--------------------|-----------------------------|------------|
| Liebherr | A320 | Inspect, Overhaul, Repair and Inspect (Test) | Reheater | 755B0000-02 | CMM 21-51-08 | 8/22/2008 |
| Liebherr | A320 | Inspect, Overhaul, Repair and Inspect (Test) | Reheater | 755B0000-02 Amdt A | CMM 21-51-08 | 8/22/2008 |
| Liebherr | A320 | Inspect, Overhaul, Repair and Inspect (Test) | Reheater | 755C0000-01 | CMM 21-51-08 | 8/22/2008 |
| HS Marston | A320 | Overhaul, Repair, Inspect and Test | Air Cooled Oil Cooler | D1979-200A | CMM 49-90-01 | 6/5/2009 |
| Hamilton Sundstrand | Aerocommander 680 Citation 500 Falcon 20 EMB110P | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 744205-3 | CMM 21-51-17 | 10/28/2005 |
| HS Marston | Airbus A320 | Repair, Inspect and Test | Bearing Air Cooler | D1876-1000A | CMM 75-22-41 DER QTC 2009-2 | 4/3/2009 |
| Honeywell | ALX | Overhaul Inspect Repair and Test | Heat Exchanger | 194546-4 | CMM 21-51-64 | 1/10/2011 |
| Honeywell | B727-200, DC8 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 184360-1 | CMM 21-50-27 | 8/21/2009 |
| Honeywell | B737 & B737 - 200 thru 900 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 182820-1-1 | CMM 21-50-14 | 8/13/2010 |
| Honeywell | B737 & B737 - 200 thru 900 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 182820-2 | CMM 21-50-14 | 8/13/2010 |
| Honeywell | B737 & B737 - 200 thru 900 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 182820-3 | CMM 21-50-14 | 8/13/2010 |
| Honeywell | B747 | Overhaul, Repair Inspect and Test | Turbine Wheel Air Flow Sensor | 948692-1 | CMM 21-30-54 | 11/17/2008 |
| Honeywell | B747 | Overhaul, Repair Inspect and Test | Turbine Wheel Air Flow Sensor | 948692-2 | CMM 21-30-54 | 11/17/2008 |
| Rosemont Inc. | B-747 | Inspect and Test | Mass Flow Sensor | 123BK4 | CMM 31-32-11 | 2/16/2009 |
| Hamilton Sundstrand | B747/PW4000/ CF6-89C2 | Overhaul, Repair Inspect and Test | Fan Air Temperature Sensor | 790390-1 | CMM 36-11-13 | 12/10/2008 |
| Hamilton Sundstrand | B747/PW4000/ CF6-89C2 | Overhaul, Repair Inspect and Test | Fan Air Temperature Sensor | 790390-2 | CMM 36-11-13 | 12/10/2008 |

| | | | | | | |
|---------------------|-----------------------|--|----------------------------|------------|--------------|------------|
| Hamilton Sundstrand | B747/PW4000/ CF6-89C2 | Overhaul, Repair Inspect and Test | Fan Air Temperature Sensor | 790390-3 | CMM 36-11-13 | 12/10/2008 |
| Hamilton Sundstrand | B747/PW4000/ CF6-89C2 | Overhaul, Repair Inspect and Test | Fan Air Temperature Sensor | 790390-4 | CMM 36-11-13 | 12/10/2008 |
| Hamilton Sundstrand | B747/PW4000/ CF6-89C2 | Overhaul, Repair Inspect and Test | Fan Air Temperature Sensor | 790390-5 | CMM 36-11-13 | 12/10/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-1 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-2 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-4 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-5 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-6 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-7 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-9 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-102 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-104 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-105 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-114 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-115 | CMM 21-52-02 | 7/2/2008 |
| Hamilton Sundstrand | B777 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 810208-117 | CMM 21-52-02 | 7/2/2008 |

| | | | | | | |
|----------------------------------|--|-------------------------------------|--|---|--|-------------------------------|
| Dukes Aerospace | BAE 146 | Inspect, Overhaul, Repair, Test | Anti-Ice Valve Assembly | 1978-300-1 Alt PN: 2-303-969-01 | CMM 75-10-01 | 1/28/2022 |
| Hamilton Sundstrand | Beech 1900 | Overhaul Inspect Repair and Test | Air Cycle Machine | 775635 - Series | CMM 21-51-33 | 1/14/2014 |
| Janitrol | Beech 1900 | Overhaul Inspect Repair and Test | Temperature Control and Shutoff Valve | 114-380040- 1/13 (22E69- 1/3) | Instruction 33E25-1 RS QTC-2020-004 | 3/10/2015 REV 3/25/2020 |
| GE Aviation | Beech 1900 | Overhaul Inspect Repair and Test | Valve and Actuator Assembly | BYLB50474/-1 Alt PN: 99-380010-1 | 21-00-01 | 5/17/2016 |
| Janitrol Aero | Beech 1900 | Overhaul, Repair, Inspect and Test | 450F Manifold temperature Sensor | 22E24 Series 129-380001-5 and 11 Alt PN: 114-380040-5 and -11 | Janitrol Instruction 33E23-1 | 12/21/2016 |
| Stewart Warner | Beech 1900 | Overhaul, Repair, Inspect and Test | Pre-Cooler | 114-380002-1 and -5 Alt PN: 10657B/D | QTC Repair Specification - OP Spec - Limited Rating. | 1/25/2017 |
| GE Aviation | Beech 1900 | Inspect, Overhaul, Repair, and Test | Valve and Actuator Assembly | BYLB50824 Alt PN: 114-380039-1 | CMM 21-00-02 | 11/15/2019 |
| Janitrol Aero | Beech 1900D | Inspect, Overhaul, Repair and Test | Temperature Control and Shutoff Valve | 51E07-1/ 4 Alt P/N: 129-380001-1/ 13 | RS QTC-2018-006 | 8/20/2018 |
| Janitrol/Midland-Ross | Beech 99 | Overhaul Inspect Repair and Test | Bleed Air Valve | 99-380011-5 (20E85-2/3) | CMM 21-10-02 | 1/13/2015 |
| EATON | Beech King Air 300 Beech 1900 | Inspect, Overhaul, Repair, Test | Electric Motor Driven Variable Delivery Hydraulic Packaged | PPEV3-011-12A/B/C/D PPEV3-011-13/A/B/C Beech PN: | CMM 29-11-19 | 5/16/2022 |
| Janitrol | Beech1900 | Overhaul Inspect Repair and Test | Pressure Regulating and Shutoff Valve | 24E88- Series Alt PN:114-380042-15,-17 | Instruction 33E24-1 | 12/8/2015 |
| Aerospace Systems and Components | Beechcraft King Air Variants | Inspect, Overhaul, Repair, Test | Solenoid Shutoff Valve, De-Ice | 4706-24 Alt PN: 101-381000-9 | RS QTC-2021-002 (iCMM 30-10-10) | 4/30/2021 |
| Stewart Warner/Harrison | Beechcraft, King Air, C90,C90A, C90GT, E90 | Overhaul Inspect Repair and Test | Oil Cooler | 8533839 Alt PN: 50-389048-Series 8001467, 10021A, 8546949 | HES-62-77F | 4/12/2013 |
| Dowty Aerospace (Triumph) | Beechjet 400 / A | Inspect, Overhaul, Repair, and Test | Hydraulic Valve Package Assembly | 2-7792 Beech PN: 45AS65022-23 | CMM 29-20-01 | 4/29/2020 |
| Dowty Aerospace (Triumph) | Beechjet 400 / A | Inspect, Overhaul, Repair, Test | Hydraulic Package | 2-7791-1 Beech PN: 45AS65021-015 Mitsubishi PN: 45A65502-31 | CMM 29-10-01 | 4/29/2020 |
| Dukes | Beechjet 400 / A / XP | Inspect, Overhaul, Repair, and Test | 3 Way Solenoid Valve | 1897-00-X Alt PN: 45AS63013-00X | RS QTC-2019-006 (iCMM 21-60-1X) | 11/6/2019 |

| | | | | | | |
|-------------------------------|--------------------------|-------------------------------------|----------------------------|---------------------------------|------------------------------------|------------|
| Electromech Technologies, LLC | Beechjet 400-400XP | Inspect, Overhaul, Repair, Test | Fuel Shutoff Valve | EM4019-2 (45AS48002-005) | RS QTC-2020-009 (iCMM 28-20-10) | 10/2/2020 |
| Honeywell | Boeing 757, 767 | Overhaul, Repair, Inspect and Test | 6" Check Valve | 3202130-1 | CMM 36-11-31 | 5/25/2016 |
| Honeywell | Boeing 757, 767 | Overhaul, Repair, Inspect and Test | 6" Check Valve | 3202130-2 | CMM 36-11-31 | 5/25/2016 |
| Honeywell | Boeing 757, 767 | Overhaul, Repair, Inspect and Test | 6" Check Valve | 3202130-3 | CMM 36-11-31 | 5/25/2016 |
| Allied Signal (Honeywell) | Boeing 737 | Inspect, Overhaul, Repair, and Test | Water Separator | 183010 - 3/4 | CMM 21-70-06 | 4/29/2020 |
| Honeywell | Boeing 737, Airbus A340 | Overhaul Inspect Repair and Test | Oil Cooler | 160564-1 | CMM 49-94-32 | 10/17/2011 |
| Honeywell | Boeing 737, Airbus A340 | Overhaul Inspect Repair and Test | Oil Cooler | 160564-2 | CMM 49-94-32 | 10/17/2011 |
| Honeywell | Boeing 737-300 thru -900 | Overhaul, Repair Inspect and test | Hi-Stage Regulator | 107484-2 | CMM 36-13-93 | 10/14/2011 |
| Honeywell | Boeing 737-300 thru -900 | Overhaul, Repair Inspect and test | Hi-Stage Regulator | 107484-3 | CMM 36-13-93 | 10/14/2011 |
| Honeywell | Boeing 737-300 thru -900 | Overhaul, Repair Inspect and test | Hi-Stage Regulator | 107484-4 | CMM 36-13-93 | 10/14/2011 |
| Honeywell | Boeing 737-300 thru -900 | Overhaul, Repair Inspect and test | Hi-Stage Regulator | 107484-5 Alt PN: 10-62008-31 | CMM 36-13-93 | 10/14/2011 |
| Honeywell | Boeing 737-300 thru -900 | Overhaul, Repair Inspect and test | Hi-Stage Regulator | 107484-6 Alt PN: 10-62008-39 | CMM 36-13-93 | 10/14/2011 |
| Honeywell | Boeing 737-300 thru -900 | Overhaul, Repair Inspect and test | Hi-Stage Regulator | 107484-7 Alt PN: 10-62008-42 | CMM 36-13-93 | 10/14/2011 |
| Honeywell | Boeing 767 | Overhaul, Repair, Inspect and Test | 9" Check Valve | 3202122-1 | CMM 21-58-03 | 5/25/2016 |
| UTAS (Hamilton Sundstrand) | Boeing 767-200/300 | Inspect, Overhaul, Repair and Test | Fan Air Temperature Sensor | 773284-X Alt PN: S210T120-XX | CMM 36-12-07 RS QTC-2012-002 | 4/30/2018 |
| Hamilton Sunstrand | Boeing 787 | Inspect, Overhaul, Repair, Test | Primary Heat Exchanger | 7110118H01 | CMM 21-53-85 | 10/8/2021 |

| | | | | | | |
|----------------------|--------------------------------------|--|---|--|------------------------------------|------------|
| Hamilton Sunstrand | Boeing 787 | Inspect, Overhaul, Repair, Test | PECS/FCAC Heat Exchanger | 7010172H0 2/3/4 7010179H0 2/3/4 | CMM 21-55-04 | 10/8/2021 |
| Hamilton Sundstrand | Boeing 787 | Inspect, Overhaul, Repair, Test | Secondary Heat Exchanger | 7110119H0 1/2/3 | CMM 21-53-86 | 10/8/2021 |
| Hamilton Sundstrand | Boeing 787 | Inspect, Overhaul, Repair, Test | Quad Heat Exchanger (FCAC and Non-FCAC) | 7113609-1/2/3/4/5/6/7/8 | CMM 21-53-84 | 10/8/2021 |
| Liebherr | Bombardier Challenger 300 | Inspect, Overhaul, Repair and Test | Catalytic Ozone Converter | 264A020000/264A30000 264A40000 | ACMM 21-51-71 RS QTC-2018-0011 | 12/20/2018 |
| BFGoodrich Aerospace | Bombardier Challenger 600 | Inspect, Overhaul, Repair, Test | Fill/Drain Assembly | 3E3209-1 Alt PN: N679-2039 | CMM 38-11-25 | 7/29/2021 |
| Honeywell | Canadair CL-601/ CL-RJ (CRJ100/200) | Overhaul, Repair, Inspect and Test | 2 ½" Shutoff Valve | 979998-1 | CMM 36-11-69 | 7/17/2009 |
| Honeywell | Canadair CL-601/ CL-RJ (CRJ100/200) | Overhaul, Repair, Inspect and Test | 2 ½" Shutoff Valve | 979998-2 | CMM 36-11-69 | 7/17/2009 |
| Honeywell | Canadair CL-601/ CL-RJ (CRJ100/200) | Overhaul, Repair, Inspect and Test | 2 ½" Shutoff Valve | 979998-3 | CMM 36-11-69 | 7/17/2009 |
| Honeywell | Canadair Lear24/25/S-76/Merlin Metro | Overhaul, Repair, Inspect and Test | Regulating Shutoff Valve Assembly | 3213812-1 | CMM 36-14-15 | 7/17/2009 |
| Honeywell | Canadair Lear24/25/S-76/Merlin Metro | Overhaul, Repair, Inspect and Test | Regulating Shutoff Valve Assembly | 3213812-2 | CMM 36-14-15 | 7/17/2009 |
| Honeywell | Canadair Lear24/25/S-76/Merlin Metro | Overhaul, Repair, Inspect and Test | Regulating Shutoff Valve Assembly | 3213812-4 | CMM 36-14-15 | 7/17/2009 |
| Honeywell | Canadair Lear24/25/S-76/Merlin Metro | Overhaul, Repair, Inspect and Test | Regulating Shutoff Valve Assembly | 3213812-5 | CMM 36-14-15 | 7/17/2009 |
| Honeywell | Canadair Lear24/25/S-76/Merlin Metro | Overhaul, Repair, Inspect and Test | Regulating Shutoff Valve Assembly | 3213812-6 | CMM 36-14-15 | 7/17/2009 |
| Hamilton Sunstrand | Cessna 441 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 744205-8 | CMM 21-51-17 | 10/28/2005 |
| Dukes Aerospace | Cessna 500/550/560 | Inspect, Overhaul, Repair, Test | Pressure Regulating And Shutoff Valve | 1946-00-12/ -16 Alt PN: 9912402-12/ -16 | RS QTC-2022-001 (iCMM 30-20-10) | 5/6/2022 |
| Hamilton Sundstrand | Cessna 650 | Overhaul, Repair, Inspect and Test | Vaneaxial Fan Assembly | 738846,725652-X Alt PN: 9914129-X | CMM 21-29-01 | 10/26/2016 |

| | | | | | | |
|----------------------|--------------------|--|-------------------------|---|------------------------------------|------------|
| Honeywell | CF6 Series | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | 121282-10 (DEC39-166-519) | CMM 78-31-20 | 3/18/2009 |
| Honeywell | CF6 Series | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | 121282-11 (9280M82P04) (DEC39-166-521) | CMM 78-31-20 | 3/18/2009 |
| Honeywell | CF6 Series | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | 121282-25 (DEC39-166-519) | CMM 78-31-20 | 3/18/2009 |
| Honeywell | CF6 Series | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | 121282-26 (9280M82P04) (DEC39-166-521) | CMM 78-31-20 | 3/18/2009 |
| DEC Technologies | CF6 Series | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | DEC39-166-523 | CMM 78-31-20 | 4/17/2009 |
| Pneudraulics/ Parker | Challenger 300 | Inspect, Overhaul, Repair and Test | Relief Valve | 4669-1/5 Parker PN:97275-3 | CMM 21-11-47 | 3/8/2017 |
| Hamilton Standard | Citation II (550) | Inspect, Overhaul, Repair, and Test | Air Cycle Machine | 738384-26 | CMM 21-51-16 | 8/5/2020 |
| Hamilton Sundstrand | Citation II YUN-12 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 775602-4 | CMM 21-51-17 | 10/28/2005 |
| Hamilton Sundstrand | Citation III | Inspect, Overhaul, Repair and Inspect | Heat Exchanger | 790298-1 | CMM 21-51-17 | 10/28/2005 |
| Hamilton Sundstrand | Citation III | Inspect, Overhaul, Repair and Inspect | Heat Exchanger | 790298-2 | CMM 21-51-17 | 10/28/2005 |
| Hamilton Sundstrand | Citation III | Inspect, Overhaul, Repair and Inspect | Heat Exchanger | 790298-4 | CMM 21-51-17 | 10/28/2005 |
| Hamilton Sundstrand | Citation III | Overhaul Inspect Repair and Test | Heat Exchanger | 735506 | CMM 21-59-01 | 4/4/2012 |
| Hamilton Sundstrand | Citation X | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 815160-1 | CMM 21-51-17 | 10/28/2005 |
| Hamilton Sundstrand | Citation X | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 744205-502 | CMM 21-51-17 | 10/28/2005 |
| Dukes Aerospace | CL 300 | Inspect, Overhaul, Repair, and Test | Anti-Ice PRSOV | 5385-00-X Alt PN: WBA3020G103-00X | RS QTC-2020-007 (iCMM 30-21-10) | 5/14/2020 |
| Kaiser Aerospace | CL 600 | Inspect, Overhaul, Repair, and Test | Cowl Anti-Ice PRSOV | 300013000-00X | CMM 30-22-03 | 2/4/2020 |

| | | | | | | |
|-------------------------------------|-------------------------------------|--|--|------------------------------|------------------------------------|------------|
| Honeywell | CL-600, CL-601 | Overhaul, Repair, Inspect and Test) | Primary/Secondary Air/Air Heat Exchanger | 191486-1 | CMM 21-50-52 | 10/29/2010 |
| Honeywell | CL-600, CL-601 | Overhaul, Repair, Inspect and Test) | Primary/Secondary Air/Air Heat Exchanger | 191486-2 | CMM 21-50-52 | 10/29/2010 |
| Goodrich Corporation (UTC Aerospace | CL-600, DHC-8 | Inspect, Overhaul, Repair, and Test | Heated Drain Mast Assembly | 4E3160-1 | CMM 38-30-07 | 9/15/2020 |
| Honeywell | CL600/ 601, KT-1 | Inspect, Overhaul, Repair and Test | Cooling Turbine | 586110-X Series | CMM 21-50-54 RS-QTC-2016-001 | 3/27/2017 |
| Bombardier | CL-RJ/ F-28/ F-50/ F-100 | Inspect, Overhaul, Repair and Test | Air Check Valve | 130158-1-1 | CMM 21-30- 70 | 6/20/2019 |
| HS Marston | CN212/ CN235 | Overhaul Inspect Repair and Test | Oil Cooler | D1443 Series | CMM 79-21-11 | 7/7/2010 |
| Martson/ Garrett Airesearch | CN212/ CN235 | Overhaul Inspect Repair and Test | Oil Cooler | 158410 - Series | CMM 79-21-21 | 2/12/2013 |
| Hamilton Sundstrand | Convair 680, Jetstar II, Sabreliner | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 744205-1 | CMM 21-51-17 | 10/28/2005 |
| Eaton | CRJ 100/200 | Overhaul, Repair, Inspect and Test | Pressure Switch | 21SN41-111 (601R62291-1) | CMM 28-42-04 | 3/18/2009 |
| Eaton | CRJ 100/200 | Overhaul, Repair, Inspect and Test | Pressure Switch | 21SN41-112 (601R62291-3) | CMM 28-42-04 | 3/18/2009 |
| Eaton | CRJ 100/200 | Overhaul, Repair, Inspect and Test | Pressure Switch | 21SN41-113A (601R62291-7) | CMM 28-42-04 | 3/18/2009 |
| Eaton | CRJ 100/200 | Overhaul, Repair, Inspect and Test | Pressure Switch | 21SN41-125 (604-62149-1) | CMM 28-42-04 | 3/18/2009 |
| Grimes | CRJ 100/200 | Overhaul, Repair, Inspect and Test | Precooler | 55E61-1 | CMM 21-50-01 | 6/5/2009 |
| Grimes | CRJ 100/200 | Overhaul, Repair, Inspect and Test | Oil Cooler | 63E79-1 | CMM 24-10-16 | 2/5/2010 |
| Grimes | CRJ 100/200 | Overhaul, Repair, Inspect and Test | Oil Cooler | 63E79-2 | CMM 24-10-16 | 2/5/2010 |
| Dukes Aerospace | CRJ 100/200 | Inspect, Overhaul, Repair, and Test | Cowl Anti-Ice PRSOV | 5399-00-X | RS QTC-2019-007 (iCMM 30-22-10) | 11/22/2019 |

| | | | | | | |
|------------------------|---------------------------|---------------------------------------|----------------------------------|-------------------|--------------|------------|
| Hamilton Standard | CRJ 100/200 CL601RJ | Inspect, Overhaul, Repair and Test | Heat Exchanger | 753355-4 | CMM 21-51-63 | 8/13/2010 |
| Hamilton Standard | CRJ 100/200 CL601RJ | Inspect, Overhaul, Repair and Test | Heat Exchanger | 753355-8 | CMM 21-51-63 | 8/13/2010 |
| Hamilton Standard | CRJ 100/200 CL601RJ | Inspect, Overhaul, Repair and Test | Heat Exchanger | 753355-9 | CMM 21-51-63 | 8/13/2010 |
| Bombardier | CRJ 200, 700, 900,1000 | Inspect, Overhaul, Repair and Test | Fan/ Sensor unit assembly | 601R51577-3 / -27 | CMM 21-61-29 | 12/12/2018 |
| Bombardier | CRJ 200, 700, 900,1000 | Inspect, Overhaul, Repair and Test | Fan/ Sensor unit assembly | 601R51577-1 | CMM 21-61-28 | 12/12/2018 |
| Airesearch | CRJ100/200 | Overhaul, Repair Inspect and Test | Oil Temperature Control Valve | 154615-3-1 | CMM 79-20-40 | 10/17/2008 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Water Separator | 750662-1 | CMM 21-51-29 | 8/15/2011 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Water Separator | 750662-2 | CMM 21-51-29 | 8/15/2011 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Water Separator | 750662-8 | CMM 21-51-29 | 8/15/2011 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul Inspect Repair and Test | Dual Bypass Valve | 808440-1 | CMM 21-61-61 | 10/17/2011 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul Inspect Repair and Test | Dual Bypass Valve | 808440-2 | CMM 21-61-61 | 10/17/2011 |
| Grimes | CRJ100/200 | Overhaul Inspect Repair and Test | Heat Exchanger | 13E41-1 | CMM 29-11-51 | 4/4/2012 |
| Grimes | CRJ100/200 | Overhaul Inspect Repair and Test | Heat Exchanger | 13E41-2 | CMM 29-11-51 | 4/4/2012 |
| Grimes | CRJ100/200 | Overhaul Inspect Repair and Test | Heat Exchanger | 13E41-3 | CMM 29-11-51 | 4/4/2012 |
| Grimes | CRJ100/200 | Overhaul Inspect Repair and Test | Heat Exchanger | 13E41-5 | CMM 29-11-51 | 4/4/2012 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Air To Oil Cooler | 160382-1 | CMM 49-94-12 | 1/1/2014 |

| | | | | | | |
|---------------------|------------|------------------------------------|----------------------------------|----------------|---------------|-----------|
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Air To Oil Temperature Regulator | 160366-1/2 | CMM 49-94-08 | 1/1/2014 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Oil Temperature Control Valve | 160148-1/2 | CMM 49-94-10 | 1/1/2014 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | 121754-2 | CMM 78-30-31 | 1/1/2014 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | 121754-3 | CMM 78-30-31 | 1/1/2014 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | 121754-5 | CMM 78-30-31 | 1/1/2014 |
| Hamilton Sundstrand | CRJ100/200 | Overhaul, Repair, Inspect and Test | Flexible Shaft Assembly | 121754-6 | CMM 78-30-31 | 1/1/2014 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Heat Exchanger | GG670-95008-3 | ACMM 21-52-13 | 6/17/2005 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Reheater Condenser | GG474-2053-3 | ACMM 21-52-21 | 6/21/2005 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (LH) | GG670-95048-1 | CMM 36-11-93 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (LH) | GG670-95048-3 | CMM 36-11-93 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (LH) | GG670-95048-5 | CMM 36-11-93 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (LH) | GG670-95048-7 | CMM 36-11-93 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (LH) | GG670-95048-9 | CMM 36-11-93 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (LH) | GG670-95048-11 | CMM 36-11-93 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (RH) | GG670-95048-2 | CMM 36-11-92 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (RH) | GG670-95048-4 | CMM 36-11-92 | 12/8/2015 |

| | | | | | | |
|--|---------------------------|---------------------------------------|---|--|--------------|-----------|
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (RH) | GG670-95048-6 | CMM 36-11-92 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (RH) | GG670-95048-8 | CMM 36-11-92 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (RH) | GG670-95048-10 | CMM 36-11-92 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (RH) | GG670-95048-12 | CMM 36-11-92 | 12/8/2015 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (LH) | GG690-95048-1 through -11 (Odd) | CMM 36-11-38 | 3/8/2017 |
| Liebherr | CRJ700/900 | Inspect, Overhaul, Repair and Test | Precooler (RH) | GG690-95048-2 through -12 (Even) | CMM 36-11-39 | 3/8/2017 |
| GE Aviation/ Sumitomo Precision Products | CRJ700/900 | Inspect, Overhaul, Repair and Test | Fuel/ Oil Heater | GE 4119T26P02 / 4119T36P03 - Alt PN: 55024001-11, 55029001-21 | CMM 79-21-07 | 3/8/2017 |
| Hamilton Sundstrand | Dash 8 -100 -200 - 300 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 778683-2 | CMM 21-51-50 | 5/19/2003 |
| Hamilton Sundstrand | Dash 8 -100 -200 - 300 | Overhaul, Repair, Inspect and Test | High Pressure Shutoff Valve | 778686-3 | CMM 21-32-06 | 7/8/2011 |
| Hamilton Sundstrand | Dash 8 -100 -200 - 300 | Overhaul, Repair, Inspect and Test | Nacelle Shutoff Valve Pressure Regulating and Shutoff Valve | 778686-4 | CMM 21-32-06 | 7/8/2011 |
| Hamilton Sundstrand | Dash 8 -100 -200 - 300 | Overhaul, Repair, Inspect and Test | Pressure Regulating and Shutoff Valve | 778695-1/3 | CMM 21-32-07 | 7/8/2011 |
| AiResearch Garrett (Honeywell) | DC-8 | Inspect, Overhaul, Repair, Test | Ozone Converter | 2202465-1 | CMM 21-70-08 | 4/30/2021 |
| Hamilton Sundstrand | DCH8-100 | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-4 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Sundstrand | DCH8-100 | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-8 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Sundstrand | DCH8-100 | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-12 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Sundstrand | DHC7, CL601RJ | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-2 | CMM 21-61-56 | 7/2/2010 |

| | | | | | | |
|---------------------|-------------------------|-------------------------------------|--------------------------------------|---------------------|---------------------------------|------------|
| Hamilton Sundstrand | DHC7, CL601RJ | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-6 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Sundstrand | DHC7, CL601RJ | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-10 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Standard | DHC7/ Citation II/ MU-2 | Overhaul, Repair, Inspect and Test | Precooler | 750458-1 | CMM 21-51-18 | 8/10/2009 |
| Hamilton Standard | DHC7/ Citation II/ MU-2 | Overhaul, Repair, Inspect and Test | Precooler | 750458-2 | CMM 21-51-18 | 8/10/2009 |
| Hamilton Standard | DHC7/ Citation II/ MU-2 | Overhaul, Repair, Inspect and Test | Precooler | 750458-3 | CMM 21-51-18 | 8/10/2009 |
| Hamilton Standard | DHC7/ Citation II/ MU-2 | Overhaul, Repair, Inspect and Test | Precooler | 750458-4 | CMM 21-51-18 | 8/10/2009 |
| Honeywell | DHC-8 100/200/300 | Inspect, Overhaul, Repair and Test | Oil cooler | 28E99-X | CMM 79-20-11 | 8/23/2017 |
| Hamilton Sundstrand | DHC8/Folker 50 | Overhaul, Repair Inspect and Test | Dual Heat Exchanger | 194776-2 SR1/SR2 | CMM 21-51-56 | 8/23/2006 |
| Hamilton Sundstrand | DHC8-100/-300, ATP | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-3 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Sundstrand | DHC8-100/-300, ATP | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-7 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Sundstrand | DHC8-100/-300, ATP | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-11 | CMM 21-61-56 | 7/2/2010 |
| Honeywell | Dornier 328 | Overhaul Inspect Repair and Test | Bay Temperature Sensor | 5409C000 - Series | CMM 21-61-05 | 11/6/2010 |
| Honeywell | Dornier 328 | Overhaul, Repair Inspect and Test | Heat Exchanger | 8554C000 | CMM 21-51-12 | 9/24/2013 |
| Honeywell | Dornier 328 | Overhaul, Inspect Repair and Test | Cold Air Unit | 1762D000-001 | CMM 21-51-11 | 11/12/2014 |
| Honeywell | Dornier 328 | Overhaul, Inspect Repair and Test | ECU Units | 5729C000/ -002/-003 | CMM 21-51-10 | 4/15/2015 |
| Honeywell | Dornier 328 | Overhaul, Inspect, Repair, and Test | Pressure Reducing and Shut-Off Valve | 4067B000 Series | CMM 36-11-03 RS QTC-2018-001 | 10/28/2014 |

| | | | | | | |
|----------------------|-----------------|--|---|---------------------------------------|------------------------------------|------------|
| Honeywell | Dornier 328 | Inspect, Overhaul, Repair and Test | Flow Control and Shutoff Valve | 4068B000-001 thru -003 | CMM 21-51-03 | 3/27/2017 |
| Honeywell | Dornier 328 | Inspect, Overhaul, Repair and Test | Temperature Control Valve | 5413C000 | CMM 21-61-08 | 3/27/2017 |
| Honeywell | Dornier 328 | Inspect, Overhaul, Repair and Test | Pressure Regulating and Shut-Off Valve (Turbine Starter Contol) | 3215732-3 | CMM 36-10-99 | 11/12/2018 |
| Technofan | Dornier 328 | Inspect, Overhaul, Repair and Test | Check Valve | GB2001AA1 | ACMM 21-51-24 | 8/27/2019 |
| EG&G Rotron (Ametek) | Dornier 328 | Inspect, Overhaul, Repair, and Test | Ground Cooling Fan | 011389-502 | CMM 21-51-23 | 4/29/2020 |
| Goodrich Corporation | Dornier 328 | Overhaul, Repair, Inspect and Test | Ejector Flow Control | 3D3556-01/03 | CMM 30-10-48 | 7/13/2016 |
| Rogerson Aircraft | Dornier 328 | Overhaul, Repair, Inspect and Test | Ejector Flow Control | 85100-3 | CMM 30-13-06 | 7/13/2016 |
| Honeywell | Dornier 328 Jet | Inspect, Overhaul, Repair, Test | Non-Return Valve 2 inch | 4066B000 / -002 | CMM 36-11-02 | 5/21/2021 |
| Dukes Aerospace | Dornier 328 Jet | Inspect, Overhaul, Repair, Test | Shutoff Valve | 5252-00-3 Alt PN: 02ND-36203-3 | RS QTC-2020-011 (iCMM 30-20-10) | 5/21/2021 |
| Honeywell | EMB 120 | Overhaul, Repair, Inspect and Test | Air Cycle Machine | 2204540-2, -4, -5, -6 | CMM 21-51-66 | 12/23/2016 |
| Hamilton Sundstrand | EMB 135-145 | Inspect, Overhaul, Repair and Test | Dual Heat Echanger | 816630-1 / -2 | CMM 21-51-69 | 12/12/2018 |
| Honeywell | EMB 135-145 | Inspect, Overhaul, Repair and Test | Pre-Cooler | 8583C000-002 Alt PN: 145-30609-401 | CMM 36-10-51 | 12/20/2018 |
| Hamilton Sundstrand | EMB110 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 744205-5 | CMM 21-51-17 | 10/28/2005 |
| Honeywell | EMB-120 | Overhaul, Repair, Inspect and Test | Oil Cooler | 160282-1 | CMM 79-20-46 | 1/22/2010 |
| Honeywell | EMB-120 | Overhaul, Repair, Inspect and Test | Oil Cooler | 160282-2 | CMM 79-20-46 | 1/22/2010 |
| Honeywell | EMB-120 | Overhaul, Repair, Inspect and Test | Oil Cooler | 160282-3 | CMM 79-20-46 | 1/22/2010 |

| | | | | | | |
|---------------------|----------------------------|------------------------------------|--------------------------------|--------------------------------|--|------------|
| Honeywell | EMB-120 | Overhaul, Repair, Inspect and Test | Oil Cooler | 160282-4 | CMM 79-20-46 | 1/22/2010 |
| Honeywell | EMB-120 | Overhaul, Repair, Inspect and Test | Oil Cooler | 160282-5 | CMM 79-20-46 | 1/22/2010 |
| Honeywell | EMB-120 | Overhaul, Repair, Inspect and Test | Oil Cooler | 160282-6 | CMM 79-20-46 | 1/22/2010 |
| Honeywell | EMB-120 | Overhaul Inspect Repair and Test | Heat Exchanger | 194546-3 | CMM 21-51-64 | 1/10/2011 |
| Hamilton Standard | EMB120 Shorts DHC7 | Inspect, Overhaul, Repair and Test | Heat Exchanger | 753355-1 | CMM 21-51-27 | 8/13/2010 |
| Hamilton Standard | EMB120 Shorts DHC7 | Inspect, Overhaul, Repair and Test | Heat Exchanger | 753355-2 | CMM 21-51-27 | 8/13/2010 |
| Hamilton Standard | EMB120 Shorts DHC7 | Inspect, Overhaul, Repair and Test | Heat Exchanger | 753355-3 | CMM 21-51-27 | 8/13/2010 |
| Hamilton Standard | EMB120 Shorts DHC7 | Inspect, Overhaul, Repair and Test | Heat Exchanger | 753355-6 | CMM 21-51-27 | 8/13/2010 |
| Hamilton Standard | EMB120 Shorts DHC7 | Inspect, Overhaul, Repair and Test | Heat Exchanger | 753355-7 | CMM 21-51-27 | 8/13/2010 |
| Hamilton Sundstrand | F50 | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-5 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Sundstrand | F50 | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-9 | CMM 21-61-56 | 7/2/2010 |
| Hamilton Sundstrand | F50 | Overhaul Inspect Repair and Test | DC Rotary Actuator | 745900-13 | CMM 21-61-56 | 7/2/2010 |
| Allied Signal | GI GII GIII GIV Jetstar II | Overhaul, Repair, Inspect and Test | 2 ½" Shutoff Valve | 109788-3 | CMM 49-50-75 DER QTC-2009-1 | 3/20/2009 |
| Allied Signal | GII GIII GIV | Overhaul, Repair, Inspect and Test | 2 ½" Shutoff Valve | 109788-1 | CMM 49-50-75 DER QTC-2009-1 | 3/20/2009 |
| Sundstrand | GII B | Test | Hydraulic Overheat Switch | G37-1J Alt. PN: BC10-3210-1 | Fenwal Publication 508 Gulfstream CMP 26-14 | 8/29/2005 |
| Honeywell | GII B | Inspect and Test | Cooling Turbine Thermal Switch | 203974-1 | Gulfstream II Maintenance Manual 21-01-12 Dated Aug 31/03 | 12/19/2008 |

| | | | | | | |
|---------------------------------|---|------------------------------------|--|---|--|------------|
| Gulfstream | GIV | Inspect, Overhaul, Repair, Test | Ozone Converter | 1159SCAC401-1 Alt PN: D-20224-1 | RS QTC 2021-004 (iCMM 21-21-03) | 10/5/2021 |
| Allied Signal | Ground Power Unit | Overhaul, Repair, Inspect and Test | 2 ½" Shutoff Valve | 109788-2 | CMM 49-50-75 DER QTC-2009-1 | 3/20/2009 |
| AiResearch | Gulfstream I/II | Inspect and Test | Precooler Heat Exchanger | 183680-1-1 | CMM 36-02-00 Maintenance Instruction 4-193 and 4-379 | 2/27/2009 |
| AiResearch | Gulfstream I/II | Inspect and Test | Precooler Heat Exchanger | 183680-2-1 | CMM 36-02-00 Maintenance Instruction 4-193 and 4-379 | 2/27/2009 |
| AiResearch | Gulfstream I/II | Inspect and Test | Precooler Heat Exchanger | 183680-3-1 | CMM 36-02-00 Maintenance Instruction 4-193 and 4-379 | 2/27/2009 |
| AiResearch | Gulfstream I/II | Inspect and Test | Precooler Heat Exchanger | 183680-3-2 | CMM 36-02-00 Maintenance Instruction 4-193 and 4-379 | 2/27/2009 |
| AiResearch | Gulfstream I/II | Inspect and Test | Precooler Heat Exchanger | 183680-4-1. | CMM 36-02-00 Maintenance Instruction 4-193 and 4-379 | 2/27/2009 |
| Honeywell | Hawker 560XL, 800XP, 850XP, Cessna Citation 680 | Overhaul, Repair, Inspect and Test | Heat Exchanger | 2340594 - Series | RS QTC-2017-001 | 1/30/2017 |
| Hymatic Engineering Company Ltd | Hawker 800 | Inspect, Overhaul, Repair, Test | Shut-Off Valve | B01A214128A | CMM 21-10-30 | 12/8/2020 |
| Dukes | Hawker Beechcraft 400, MU-300, | Inspect, Overhaul, Repair and Test | Pressure Regulating Shut-off Valve | 45AS66001-009 / 011 Alt PN: 1894-00-1 / 3 | RS QTC-2018-003 (iCMM 30-10-10) | 10/29/2018 |
| Dukes | Hawker Beechcraft MU-300, 400 | Inspect, Overhaul, Repair and Test | Pressure Regulating Shut-off Valve | 45AS63019-007 / 009 Alt PN: 1896-00-1 / 3 | RS QTC-2018-002 (iCMM 36-10-X) | 5/7/2018 |
| Dukes | Hawker Beechcraft MU-300, 400 | Inspect, Overhaul, Repair and Test | Pressure Regulating Shut-off Valve | 45AS66008-005 / 007 Alt PN: 1895-00-1 / 3 | RS QTC-2018-003 (iCMM 30-20-X) | 5/31/2018 |
| Dukes | Hawker Beechcraft MU-300, 400 | Inspect, Overhaul, Repair and Test | Pressure Regulating Shut-off Valve (Normally Closed) | 45AS66001-009/ 011 Alt PN: 1894-00-1 / -3 | RS QTC-2018-008 (iCMM 36-10-10) | 4/15/2019 |
| Dukes, Inc. | Hawker/ Beechcraft Various | Inspect, Overhaul, Repair and Test | Bleed Air Regulating and Shutoff Valve | 1960-00-1/ -3 Beech PN: 114-380042-19/ -21 | CMM 36-00-02 | 3/27/2017 |
| Dukes, Inc. | Hawker/ Beechcraft Various | Inspect, Overhaul, Repair and Test | Bleed Air Regulating and Shutoff Valve | 1925-00-1/ -3 Beech PN: 114-380059-3/ -5 | CMM 36-00-01 | 3/27/2017 |
| Marston Palmer | HC144 | Inspect, Overhaul, Repair and Test | Oil to Fuel Heat Exchanger | D1508-120A | CMM 73-11-12 | 2/12/2013 |

| | | | | | | |
|---------------------------------|---|---|---|---|------------------------------------|------------|
| Allied Signal | HS-125-700/BH-125/ DH-125/Bae-125-800 | Overhaul Inspect Repair and Test | Butterfly shutoff valve | 104968 | CMM 21-60-85 | 11/14/2008 |
| Hamilton Sundstrand | Jetstar II | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 744205-7 | CMM 21-51-17 | 10/28/2005 |
| Aircraft Porous Media Inc. | L-1011 | Inspect, Overhaul, Repair and Inspect (Test) | Hydraulic Filter Housing | AD-9320-202 | CMM 29-11-21 | 6/29/2008 |
| Aircraft Porous Media Inc. | L-1011 | Inspect, Overhaul, Repair and Inspect (Test) | Hydraulic Filter Housing | AD-9320-203 | CMM 29-11-21 | 6/29/2008 |
| Aircraft Porous Media Inc. | L-1011 | Inspect, Overhaul, Repair and Inspect (Test) | Hydraulic Filter Housing | AD-9320-204 | CMM 29-11-21 | 6/29/2008 |
| Aircraft Porous Media Inc. | L-1011 | Inspect, Overhaul, Repair and Inspect (Test) | Hydraulic Filter Housing | AD-9320-205 | CMM 29-11-21 | 6/29/2008 |
| Aircraft Porous Media Inc. | L-1011 | Inspect, Overhaul, Repair and Inspect (Test) | Hydraulic Filter Housing | AD-9320-206 | CMM 29-11-21 | 6/29/2008 |
| Grimes Aero | Learjet 55/60 | Inspect, Overhaul, Repair, and Test | Wing Anti-Ice PRSOV | 15E51-X Alt PN: 6600259-X | RS QTC-2020-008 (iCMM 30-10-01) | 5/28/2020 |
| Honeywell | Metro | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-5-X | CMM 36-14-11 | 4/3/2009 |
| Garrett Airesearch | Mitsubishi MU-300* | Overhaul, Repair, Inspect and Test | One-inch Diameter Pneumatic Shutoff Valve | 979494-series | Report 979494MM | 10/26/2016 |
| Hamilton Sundstrand | MU-2, Sabreliner, EMB110 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 744205-4 | CMM 21-51-17 | 10/28/2005 |
| Dynamic Controls Corporation | MU-300,Hawker Beechcraft 400/A/T (Military T-1) | Inspect, Overhaul, Repair and Test | Horizontal Stabilizer De- Ice Sequence Timer | 11218-3 Alt PN: 45AS88836-007 (-7) Alt PN: 128-384054-1 | RS QTC-2018-010 (iCMM 30-20-20) | 11/7/2018 |
| Honeywell | N/A | Test | Duct Temperature Sensor | 627962-2 | CMM 21-60-60 | 5/9/2006 |
| Hamilton Sundstrand | N/A | Inspect and Test | Bellows | 774636-3 | CMM 36-12-02 | 8/29/2008 |
| Ametek Drexelbrook | N/A | Inspect and Test | Waste Water Discharge Sensor Assembly | 899-156-612 | CMM 38-32-01 | 10/10/2008 |
| Hamilton Standard | N/A | Overhaul Inspect Repair and Test | Actuator Assembly | 754909-1 | CMM 21-61-32 | 7/2/2010 |

| | | | | | | |
|------------------------|---------------------|--|---|-------------------------------------|--------------------------------------|------------|
| Hamilton Standard | N/A | Overhaul Inspect Repair and Test | Actuator Assembly | 754909-5 | CMM 21-61-32 | 7/2/2010 |
| Harrison | N/A | Overhaul, Repair, Inspect and Test | Oil Cooler | 8546922 | Harrison HES-62-77F | 8/15/2010 |
| Custom Controls | N/A | Overhaul, Repair, Inspect and Test) | Gage Pressure Switch | 94P32 | CMM 32-21-01 | 10/29/2010 |
| Harrison | N/A | Overhaul, Repair, Inspect and Test | Oil Cooler | 114-389000 Series Alt PN: 10656D | Harrison HES-62-77F RS QTC-2006-1 | 3/15/2011 |
| IMM Marston | N/A | Overhaul, Inspect Repair and Test | Oil Cooler | D1834 Series | CMM 79-21-21 | 1/18/2012 |
| Hamilton Sundstrand | N/A | Test, Repair and Inspect | Fan Heater | 11469-00 | CMM 21-40-11 | 6/7/2016 |
| Hamilton Standard | N/A | Inspect, Overhaul, Repair and Test | Bypass Valve | 738385-X VAP-AIR PN:26941061-0X | CMM 21-61-13 | 8/28/2017 |
| Hamilton Standard | Northrop F-5 | Inspect, Overhaul, Repair, Test | Cooling Turbine | 752001-1 | TO 15A3-2-53-3 & TO 15A3-2-53-4 | 1/6/2021 |
| Hamilton Standard | Northrop F-5 | Inspect, Overhaul, Repair, Test | Refrigeration Pack | 751872-3 | TO 15A3-3-50-2 & TO 15A3-3-50-4 | 2/18/2021 |
| Hamilton Standard | Northrop F-5 | Inspect, Overhaul, Repair, Test | Dual Cabin Temp Valve | 751865-25 | TO 15A8-5-70-3 | 5/21/2021 |
| Beech/ SOCATA | PC-9/ TBM-700 | Inspect, Overhaul, Repair and Test | Cooling Turbine | 2204600-1/-2 | QTC 21-50-QTC / RS QTC-2017-002 | 9/22/2017 |
| Hamilton Sundstrand | Piaggio P180 | Inspect, Overhaul, Repair and Inspect | Heat Exchanger | 790298-3 | CMM 21-51-17 | 10/28/2005 |
| Hamilton Sundstrand | Piaggio P180 | Inspect, Overhaul, Repair and Inspect | Heat Exchanger | 790298-5 | CMM 21-51-17 | 10/28/2005 |
| Dukes | Premier 1 / 1A /390 | Inspect, Overhaul, Repair and Test | Pressure Reducing and Shut-Off Valve (Normally Open) Nacelle Anti-ice | 5188-00-1/ 7 | RS QTC-2019-001 (iCMM 75-10-02) | 3/13/2019 |
| Custom Control Sensors | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Gage Pressure Switch | 8D1496 | CMM 79-35-11 | 6/14/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Pressure Switch | 21SN04-352 | ACMM 79-09-07 | 7/23/2007 |

| | | | | | | |
|------------------------|-------------|--|---|-------------|---------------|-----------|
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Pressure Switch | 21SN04-353 | ACMM 79-09-07 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Pressure Switch | 21SN04-354 | ACMM 79-09-07 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Pressure Switch | 21SN04-355 | ACMM 79-09-07 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Oil Filter Differential Pressure Switch | 21SN04-383A | CMM 79-21-25 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Oil Filter Differential Pressure Switch | 21SN04-391 | CMM 79-21-25 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Oil Filter Differential Pressure Switch | 21SN04-391A | CMM 79-21-25 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Oil Filter Differential Pressure Switch | 21SN04-404 | CMM 79-21-25 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Oil Filter Differential Pressure Switch | 21SN04-405 | CMM 79-21-25 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Oil Filter Differential Pressure Switch | 21SN04-416 | CMM 79-21-25 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Oil Filter Differential Pressure Switch | 21SN04-417 | CMM 79-21-25 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Low Pressure Oil Switch | 21SN04-275A | CMM 79-34-15 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Scavenge Filter Pressure Switch | 21SN04-298B | CMM 79-35-16 | 7/23/2007 |
| Eaton | PW2000/4000 | Inspect, Overhaul, Repair and Inspect (Test) | Fuel Filter Differential Pressure Switch | 21SN04-300B | CMM 73-34-15 | 7/23/2007 |
| Custom Control Sensors | PW2000/4000 | Overhaul, Repair Inspect and Test | Fuel Pump Filter Differential Pressure Switch | 42D362 | CMM 73-11-10 | 1/9/2009 |
| Custom Control Sensors | PW2000/4000 | Overhaul, Repair Inspect and Test | Fuel Pump Filter Differential Pressure Switch | 42D394 | CMM 73-11-10 | 1/9/2009 |
| Custom Control Sensors | PW2000/4000 | Overhaul, Repair Inspect and Test | Fuel Pump Filter Differential Pressure Switch | 42D395 | CMM 73-11-10 | 1/9/2009 |

| | | | | | | |
|---------------------|--|--|---|--|---------------------------------|------------|
| Hamilton Sundstrand | R70 | Overhaul, Repair, Inspect and Test | Turbine and Pack Bypass Valve | 754751-1 | CMM 21-61-25 | 7/2/2010 |
| Hamilton Sundstrand | R70 | Overhaul, Repair, Inspect and Test | Turbine and Pack Bypass Valve | 754751-2 | CMM 21-61-25 | 7/2/2010 |
| Hamilton Sundstrand | R70 | Overhaul, Repair, Inspect and Test | Turbine and Pack Bypass Valve | 754751-3 | CMM 21-61-25 | 7/2/2010 |
| Hamilton Sundstrand | R70 | Overhaul, Repair, Inspect and Test | Turbine and Pack Bypass Valve | 754751-4 | CMM 21-61-25 | 7/2/2010 |
| Hamilton Sundstrand | R70 Refrigeration Pack | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 775602-1 | CMM 21-51-17 | 10/28/2005 |
| Hamilton Sundstrand | R70 Refrigeration Pack | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 775602-2 | CMM 21-51-17 | 10/28/2005 |
| Hamilton Sundstrand | S76 | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 769130-2 | CMM 21-51-35 | 12/7/2005 |
| Whittaker Corp. | Saab 340 | Overhaul, Repair, Inspect and Test | Pressure Actuated Butterfly Valve | 321935 | CMM 36-11-20 | 2/5/2010 |
| Whittaker Corp. | Saab 340 | Overhaul, Repair, Inspect and Test | Pressure Actuated Butterfly Valve | 321945 | CMM 36-11-20 | 2/5/2010 |
| Hamilton Sundstrand | SAAB 340 | Overhaul, Repair, Inspect and Test) | Dual Heat Exchanger | 779215-1 | CMM 21-51-43 | 8/13/2010 |
| Hamilton Sundstrand | SAAB 340 | Overhaul, Repair, Inspect and Test) | Dual Heat Exchanger | 779215-2 | CMM 21-51-43 | 8/13/2010 |
| Hamilton Sundstrand | SAAB 340 | Overhaul, Repair, Inspect and Test) | Pressure Regulating and Shutoff Valve | 785802-1 | CMM 21-51-52 | 11/12/2010 |
| Hamilton Sundstrand | SAAB 340 | Overhaul, Repair, Inspect and Test) | Pressure Regulating and Shutoff Valve | 785802-2 | CMM 21-51-52 | 11/12/2010 |
| Hamilton Sundstrand | SAAB 340 | Overhaul, Repair, Inspect and Test) | Pressure Regulating and Shutoff Valve | 785802-3 | CMM 21-51-52 | 11/12/2010 |
| Harrison / Lori | Socata | Inspect, Overhaul, Repair and Test | Oil Cooler | L8538233 Harrison PN: 8538233 / SW 10717C | Harrison SB HES-62-77F | 2/7/2018 |
| Dukes Aerospace | T-6 Texan II (Beechcraft Model 3000 Defense) | Inspect, Overhaul, Repair, Test | Bi-Level Flow Control and Shutoff Valve | 1997-00-3 | RS QTC-2020-010 (iCMM 21-30-15) | 10/20/2020 |

| | | | | | | |
|---------------------|----------------|--|------------------------|-----------|--------------|------------|
| Sundstrand | Twin Commander | Inspect, Overhaul, Repair and Inspect (Test) | Condenser | 729308 | CMM 21-50-01 | 12/20/2006 |
| Hamilton Sundstrand | Twin Commander | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 727493 | CMM 21-50-01 | 12/20/2006 |
| Hamilton Sundstrand | Twin Commander | Inspect, Overhaul, Repair and Inspect (Test) | Precooler | 727494 | CMM 21-50-01 | 12/20/2006 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-1 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-3 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-4 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-5 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-6 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-7 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-8 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-9 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-10 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-11 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-12 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-13 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-14 | CMM 21-61-29 | 9/8/2004 |

| | | | | | | |
|---------------------|---------|------------------|--------------------------------|-----------|--------------|-----------|
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-15 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-16 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-17 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750659-18 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-1 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-2 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-3 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-4 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-5 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-6 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-7 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-8 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-9 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Standard | Various | Inspect and Test | Overtemperature Switch | 750665-10 | CMM 21-61-29 | 9/8/2004 |
| Hamilton Sundstrand | Various | Test | Cabin/ Duct Temperature Sensor | 754681-1 | CMM 21-61-24 | 9/17/2004 |
| Hamilton Sundstrand | Various | Test | Cabin/ Duct Temperature Sensor | 754691-1 | CMM 21-61-24 | 9/17/2004 |

| | | | | | | |
|----------------------------------|---------------------------|--|--------------------------------|----------------------|--|------------|
| Hamilton Sundstrand | Various | Test | Cabin/ Duct Temperature Sensor | 754691-2 | CMM 21-61-24 | 9/17/2004 |
| Hamilton Sundstrand | Various | Test | Cabin/ Duct Temperature Sensor | 754691-3 | CMM 21-61-24 | 9/17/2004 |
| Hamilton Sundstrand | Various | Test | Cabin/ Duct Temperature Sensor | 754691-5 | CMM 21-61-24 | 9/17/2004 |
| Hamilton Sundstrand | Various | Inspect, Overhaul, Repair and Inspect (Test) | Heat Exchanger | 744205-2 | CMM 21-51-17 | 10/28/2005 |
| Honeywell | Various | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-1 | CMM 36-14-11 | 4/3/2009 |
| Honeywell | Various | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-2 | CMM 36-14-11 | 4/3/2009 |
| Honeywell | Various | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-3 | CMM 36-14-11 | 4/3/2009 |
| Honeywell | Various | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-4 | CMM 36-14-11 | 4/3/2009 |
| Honeywell | Various | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-6 | CMM 36-14-11 | 4/3/2009 |
| Honeywell | Various | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-7 | CMM 36-14-11 | 4/3/2009 |
| Honeywell | Various | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-8 | CMM 36-14-11 | 4/3/2009 |
| Honeywell | Various | Overhaul, Repair Inspect and Test | Low Limit Temperature Sensor | 129542-10 | CMM 36-14-11 | 4/3/2009 |
| Rosemount Aerosp | Various | Inspect, Overhaul, Repair and Test | Pitot Tube | 0851GW/ 0851GW-1 | CMM 34-10-73 | 3/27/2017 |
| Garrett Airesearch | Various | Test | Temperature Selector Valve | 32104056-X Series | Garrett AiReseach Report No 21-63-13 RS QTC-2017-003 | 4/19/2017 |
| Custom Controls | Various | Inspect, Repair, Test | Case Assembly | 16-339/ 361/ 364/369 | CMM 73-11-10 / QTI-2007-3 | 2/12/2018 |
| Hawker Siddeley Dynamics Limited | Various Hawker Beechcraft | Inspect, Overhaul, Repair, Test | Non-Return Insert Type | AWE124-49 / 51 /55 | CMM 21-30-6 | 6/1/2021 |